ENGINEERING MODIFICATION NOTICE (CANADA)

CEMN NO. 1259

DATE 23 Oct 73 | TMC (Canada) LTD OTTAWA ONTARIO | SHEET 1 OF 1

MODEL AFFECTED: LMC-32 | LCR NO. 50

SECTION AFFECTED: A10812 - P.C. BOARD & M/L

ORIGINATOR: A. PETROFF | APPROVAL: | FINAL APPROVAL:

DISTRIBUTION

DEPT.	CEMN	DOC.	SIGN	DEPT.	CEMN	DOC.	SIGN
ENG. CO-ORD				STOCK & INV.			
ENG. STDS.				QUAL. ASSUR.			
ENG. ADMIN.				MASTER FILE 0			
PURCHASING				MASTER FILE 1			
METHODS				MASTER FILE 2			
PROD. PLANNING				MASTER FILE 3			
DATA CONTROL							
MATL. CONTROL							

DOCUMENTS AFFECTED

TYPE: DWG ☑ LIST NPL ☐ ML ☑ SPEC. ☐

DOCUMENT NO.	REV.	CHD.
A10812-1 TO -5	A	[illegible]
A10812-5 M/L	Ø	[illegible]

DESCRIPTION

CHANGES :-

A10812-5 - 'C14' WAS MISSING, 'C15' WAS CHANGED TO READ 'C5'

A10812-1 & -2 - HEATSINKS MTG. HOLES WERE ADJUSTED TO THE CORRECT HOLE SPACING.

A10812-3 - DESIGNATIONS CHANGED TO AGREE WITH A10812-5 CHANGES

A10812-4 - ISSUE RAISED.

A10812-5 M/L RELEASED AT ISSUE Ø

REASON FOR CHANGE

☐ TO AGREE WITH CEMN NO. PERTAINING TO:

☑ ERROR

OTHER:

DISPOSITION OF STOCK	DEPLETE ☐	DISCARD ☐	MODIFY ☐	CONFORMS. ☐	NO STOCK ☐	NOT AFFECTED ☐
	REMARKS					

PRICE CHANGE	NONE ☐	INCREASED BY	DECREASED BY
MODIFICATION EFFECTIVE	IMMEDIATELY (ALL NEW PARTS) ☐	SPECIFIC DATE	REMARKS
	NEXT PROD. RUN ☐	SERIAL NO. MFGR. NO. JOB NO.	

AFFECTED SUPPORTING DOCUMENTS (ENG. INFO.)	STATUS	LIST	ASSY	SCHEM	SPEC.					REMARKS
	CHGD.									
	CEMN NO.									
	N/A									
	CONF.									