

S1045

TMC SPECIFICATION															NO. S 1045		
REV:	<input checked="" type="checkbox"/>																
COMPILED:	<i>L. Gabriel</i>					CHECKED:	<i>12/2/65</i>			APPD:	<i>L. J. [Signature]</i>		SHEET	1	OF	2	
TITLE:	TTR-10 TO TTR-11 LIST CONVERSION																

12/9/45

I. TO CONVERT A TTR-10 TO TTR-11 FOR USE WITH THE TTC-1, MAKE THE FOLLOWING CHANGES.

A. On TTR-10 List (To convert to TTR-11)

- 1. Chg AX418 to AX418-2; MAIN CHAS ASSY.
- 2. Chg all A2792 Refs and U/O to A2792-2.
- 3. Add 1 ea CK1079; DIAG,INTCON.

B. On AX418 List (To convert to AX418-2)

- 1. Dele 1 ea MS4167; COV,TB CUTOUT.
- 2. Dele 1 ea A4045; DETENT ASSY,REAR.
- 3. Dele 1 ea LWE04MRN; Chg qty fr 150 to 149; Chg U/T/M fr MS4167 (4) to TM100-11 (3).
- 4. Dele 4 ea SCBP0440BN5; U/T/M MS4167; Chg qty fr 20 to 16.
- 5. Chg DT108 U/O fr A4045 to A4312; DETENT, SW-30 DEG.
- 6. Chg LD1644/MS4113 U/O fr A4045 to A4312; PL,DETENT.
- 7. Add X ea BS100; SOLDER,TIN ALY; U/O CA1143.
- 8. Add X ea CD101-1MW; CD,NYLON,LACING; U/O CA1143.
- 9. Add 2 ea LWS04MRN; U/T/M WS138; U/O A4312; Chg qty fr 2 to 4.
- 10. Add 2 ea MS154-1; U/T/M TM100-11; U/O AX418-2; Chg qty fr 4 to 6.
- 11. Add 5 ea MWC24/7/U0; U/O CA1143.
- 12. Add 9 ea MWC24/7/U2; U/O CA1143.
- 13. Add 9 ea MWC24/7/U4; U/O CA1143.
- 14. Add 9 ea MWC24/7/U5; U/O CA1143.
- 15. Add 22 ea MWC24/7/U6; U/O CA1143.
- 16. Add 9 ea MWC24/7/U9; U/O CA1143.
- 17. Add 2 ea NTH0440BN6; U/O A4312; Chg qty fr 6 to 8.

TMC SPECIFICATION

NO. S 1045

REV:

COMPILED:

CHECKED:

APPD:

SHEET 2

OF 2

TITLE: TTR-10 TO TTR-11 LIST CONVERSION

18. Add 8 ea PX100-1-234; U/O CA1143; INS SLVG-SZ 3.
19. Add 1 ea PX337-11; INS,TERM.BD; U/T/M TM100-11; U/O AX418-2.
20. Add 6 ea SCBP0440BN10; U/T/M WS138 (2); U/O A4312; and U/T/M TM100-11 (4); U/O AX418-2; Chg qty fr 8 to 14.
21. Add 1 ea TE104-1; TERM.,LUG-LKG; U/T/M TM100-11; U/O AX418-2.
22. Add 2 ea TE117-28; SPACER,SLV; U/O A4312.
23. Add 1 ea TM100-11; TERM.BD-BARR; U/O AX418-2; Sym TB1502.
24. Add 4 ea WA109-17; WASH.,NM; U/O A4312.
25. Add 1 ea WS138; SW SECT.,ROT.; U/O A4312; Sym S1514.
26. Add 1 ea A4312; SW ASSY; TTC; U/O AX418-2.
27. Add 1 ea CA1143; WRG HARN,BRCHD; U/O A4312.
28. Add 1 ea CK1079; DIAG,INTCON.
29. Chg all AX418 Refs & U/O to AX418-2.

C. Ref Mod KIT-252.

