DATE 24/6/60 R.W.T.

TMC SPECIFICATION NO. S-10036

TITLE: PRODUCTION TESTING OF CRYSTAL B.F.O.

JOB

APPROVED R. N.J.

GPR-90-RX MOD. CAN-1B

INSTRUCTIONS

FOR THE

PRODUCTION TESTING OF CRYSTAL B.F.O.

GPR-90-RX MOD. CAN-1B

TMC SPECIFICATION NO. S-10036

SH. 2 OF 4
COMPILED BY R.W.T.

TITLE: PRODUCTION TESTING OF CRYSTAL B.F.O.

APPROVED

GPR-90-RX MOD. CAN-1B

INDEX

		Page
1.	Test Equipment Required	3
2.	Test Instructions	1+
3.	Applicable Drawings	14

DATE 24/6/60 SH. 3 OF 4

R.W.T.

TMC

TITLE:

SPECIFICATION NO. S-10036

PRODUCTION TESTING OF CRYSTAL B.F.O.

JOB

APPROVED

GPR-90-RX MOD. CAN-1B

1.

TEST EQUIPMENT REQUIRED

- 1.1 Oscilloscope; Tektronix Model 545 with type 53/54B drawer.
- 1.2. Counter; Berkeley Eput Meter Model 5558.
- 1.3. Power Supply Unit; 150V DC stabilized 6.3V A.C.
- 1.4. 4 pin plug to octal socket adaptor.

DATE 24/6/60 SH. 4 OF 4

R.W.T.

TMC SPECIFICATION NO. S-10036

TITLE: PRODUCTION TESTING OF CRYSTAL B.F.O.

APPROVED

GPR-90-RX MOD. CAN-1B

100

JOB

2. TEST INSTRUCTIONS

2.1. General and Visual Inspection

- 2.1.1. Inspect the unit for obvious electrical and mechanical errors by comparison with the prototype.
- 2.1.2. Ensure particularly that there are no dry joints or short circuits.
- 2.1.3. Check that soldered connections to the crystal unit have been made at the tips of the pins using a heat shunt.
- 2.1.4. Check that screws are tight.

2.2. <u>Electrical Performance Tests</u>

- 2.2.1. Connect the crystal B.F.O. to the power supply by means of the adaptor provided and switch on.
- 2.2.2. Give the crystal B.F.O. a minimum of 5 minutes to warm up.
- 2.2.3. Connect the output of the crystal B.F.O. to the oscilloscope and the "Vertical Signal Out" terminal on the oscilloscope to the input of the Counter.
- 2.2.4. Measure the peak-to-peak amplitude of oscillation on the scope. This should be within 10% of 1 volt.
- 2.2.5. Measure the frequency of oscillation on the counter. This should be between the limits 452.465 kc/s and 452.445 kc/s.

3. APPLICABLE DRAWINGS.

A-10267

Assembly.

CK-10315

Schematic.

ML-10097

Material List.