TMC SPECIFICATION NO. S-410

COMPILED CHECKED TITLE: Production Tost of M dol SEE-2

APPROVED

COMPLETE PRODUCTION TEST

INSTRUCTIONS FOR

TMC MODEL SBE-2

TRANSMITTING MODE SELECTOR

DATE 8-24-64 SHEET 2 OF 18		TMC SPECIFICATION NO. 5 -410	E
COMPILED	CHECKED	TITLE: Produ tion T st f Model SBE-2	
APPROVED			

# TEST EQUIPMENT REQUIRED

Hewlett Packard	Model	524-C	Frequency Count r
Ballentine	11	314	A.C. Voltmeter
Hewlett Packard	#	ЫÓВ	VTVM
Hewlett Packard	#	200CD	Audio Generator
THC	W	PTE-3	Spectrum Analyser
Heath Kit	91	AV-3	VTVM
Crystal.		TMC Type CR-27/U	2.000 MC
Crystal		TMC Type CR-27/U	4.000 MC
Crystal		TMC Type CR-27/U	2.270 MC
Crystal		TMC Type CR-27/U	4.270 MC

# 70-02 Watt Resistor

1 Megohm Resistor & Watt

DATE 8-24-64 SHEET 3 OF 18		TMC SPECIFICATION NO. 5 -410	E
COMPILED	CHECKED	TITLE: Production Test of Med 1 SBE-2	
APPROVED			

## \*A. PRELIMINARY:

- 1. Inspect the unit for mechanical imperfections, proper type and placement of filters, vacuum tubes/ and bvious wiring errors. Attach jumper to terminals 2 & 3 f E-101.
- 2. Check the even heaters by measuring the resistanc between pins D and E of J-109. For 115 V AC connections this value should be 300 + 10%; for 230 V AC conn ctions 600 + 10%.
- 3. Check ALDC circuitry as follows: From J113 to ground (chassis) reading should be 470 K + 10%; From J113 to pins 2 and 7 of V113 reading should be 23K + 10% in each case.
- 4. Check to insure that the RF and MF dial calibration marks line up with the Red line at the counterclockwis dial stop.
- 5. Connect the 70 n load to the RF Output connector J-103.
- 6. Place test crystals in the oven as fillows:

Position	Frequency
1.	2.0 me
2.	4.0 mc
3.	2.27 mc
4.	4.27 mc

- 7. Connect the unit to the power supply and apply AC pow r. The Oven and Dial lamps should light up. After a bri f warmup period, when even lamp commences to cycl ON and OFF, proceed with the tests below.
- 8. With the Meter Switch in the CAL position, adjust th CAL potentiometer for ZERO reading of Meter M-101.

# \*B. 17KC Oscillator Check:

1. With the VTVM at Pin 4 of TlO5, measure Output Voltage. The reading should be between .9 and 2.4 volts.

NOTE: Indi ate compl tion and ace ptance of portion(s) of this test prec ded by (\*) by recording r quired ebserved value or by check (./) mark as requir d on attach d test Data Sheets.

DATE 8-24-64 HEET 4 OF 18		TMC SPECIFICATION NO. 5 -410	E
COMPILED	CHECKED	TITLE: Production Test of Model SBE-2	
APPROVED			

2. With the Frequency Counter check the frequency of the 17 Kc Oscilletor at Pin 4 of T-105. Should read 17 K + 8.5 cps at 70°c.

## \*C. 287 KC Oscillator Check:

- 1. With the VTVM at Pin 8 of Zl03 or at the arm of Rll3, measure the Output Voltage. The reading should b between .7 and 1.5 volts.
- 2. Remove the VTVM and connect the frequency count r to Pin 8 of Z103 or the arm of R113. Adjust C-120 as necessary to bring 287Kc Oscillator on frequency. Should be 287 Kc + 57.4 cps at 70 c.

## \*D. Modulator Tests:

- 1. LSB Carrier Balance
  - a. LSB, USB Switches in OFF or minimum position.
  - b. Carrier Insert fully CCW, minimum.
  - c. Connect VTVM across output of Z101 (LSB) filt r.
  - d. Adjust R110 for minimum indication on VTVM.
  - e. Repeat above test for Z102 (USB) filter and R-112.
- #2. 287Ke Modulator and 270 Kc Amplifier:
  - a. LSB-USB Controls off or minimum.
  - b. Set R113 Potentiameter and C259 to MID Position.
  - c. Set C258 for maximum capacitance.
  - d. Carrier Insert Maximum CW.
  - e. Connect VTVM to Pin 2 or 7 of V113.
  - f. Tune T108 and T107 bottom and top slugs for maximum output. Reduce carrier insert as necessary to prevent broad responsive tuning.

NOTE: Indicat completion and acceptan e of p rticm(s) of this test proce ded by (\*) by r rding required obs rved valu or by check (/) mark as required on attached test Data She ts.

DATE 8-24-64 SHEET 5 OF 18		TMC SPECIFICATION NO. S -410		E
COMPILED	CHECKED	TITLE:	Produ tion T st f Model SBE-2	
APPR	OVED			

- g. Remove VTVM and connect Frequency counter at Pin 2 or 7 of V113 and read frequency of 270 KC. This is the proper modulation product.
- h. Carrier Insert minimum, CCW.
- i. Connect VTVM to pin 7 of Vl09A and balance out 287 KC completely with Rl13 and G259.
- j. Lock nuts.

## \*E. Audio & Sideband Reversal Test.

- #1. Microphone Input.
  - a. Connect the AF generator unbalanced cutput in series with 1 megchm resistor to pin 1 f Mik Input jack and thence to ground, Pin 2.
  - b. Set the USB and LSB Selector switches to OFF and Carrier Insert to minimum.
  - c. Set RF Bandswitch to position 2-4 mcs.
  - d. Turn LSB Selector switch to Mike position. With the AF generator set to 1000 cps and an output f.05 volt, adjust the LSB Gain control for a deflection of 100% on LSB meter position. This point on the gain centrol should be reach d b fore its maximum gain position.
  - LSB filter Z-101 on the 0-1 volt scale. N to output indication. Turn RF Bandswitch t th 4-8 mes band the output indication should now be transferred from the LSB filter Z-101 to th output of the USB filter Z-102.

## #2. Channel 1 Input.

- a. Connect the AF generator balanced output to t rminals 6 and 8 of E-101 with a twisted shielded pair and shield connected to terminal 7 thenc by jumper to terminal 5, ground.
- c. Set USB and LSB Selector switches to OFF and Carrier Insert to minimum.

NOTE: Indicat completion and ac eptance of portion(s) of this t st pr c ded by (\*) by r ording required bs rved value or by check (/) mark as required on attach d t st Data She ts.

DATE 8-24-64 SHEET 6 OF 18		TMC SPECIFICATION NO. 5 -410	
COMPILED	CHECKED	TITLE: Production T at f M del SEE-2	
APPROVED			

- e. Set RF Bandswitch to position 2-4 mcs.
- d. Turn LSB Selector switch to Channel I position. With the AF generator set to 1000 cps and an output of .05. volt, as measured across one side of the AF generator balanced output and ground. Adjust the LSB Gain control for a deflection of 100% on the LSB meter position. This point on the gain control should b rached before its maximum gain position.
- e. Connect the VTVM across the Output terminals of LSB filter Z101 on the 0-1 volt scale. Note output indication. Turn RF bandswitch to the 4-8 mcs band the output indication should now be transferred from the LSB filter Z101 to the output of the UBB filter Z102.

## #3. Channel 2 Input.

- a. Connect the AF generator balanced output t trminals 10 and 12 of E-101 with a twisted shi ld d
  pair and shield connected to terminal 11 thenc
  by jumper to terminal 9, ground.
- b. Repeat the tests for paragraphs b thru of Channel l Input above, with the exception that USB should be substituted for LSB and vice versa, ZlOl f r ZlO2 and vice versa. Requirements remain as f r Channel l Input above.

## \*F. VOX Tests:

#### #1. Gain

- a. Set VOX gain R-140 to maximum.
- b. All other gain controls to minimum.
- c. Increase Carrier Insertion R-106 until th Exciter Lamp and Relay K-101 energiz as indicated by 5 ohms resistance from terminal 4 of E101 to ground.
- d. With the VTVM on Pin 2 of VIIO a reading f .17 to .5 velt should be obtained.
- e. With the Carrier Insertion R-106 redu d t

HOTE: Indicat completion and acceptan e f portion(s) f this test pre ded by (\*) by recording r quired observed value or by check (√) mark as required on attached test Data Sheets.

DATE 8-2	of 18	TMC SPECIFICATION NO. S -410	
COMPILED	CHECKED	TITLE: Produ tion Test of Mod 1 SBE-2	
APPROVED			

minimum, the Exciter Lamp and Relay K-101 should deenergise as indicated by infinite resistant from terminal 4 of E101 to ground.

- f.. Set the Transmitter switch S-104 to ON, the r sistance reading from terminal 4 to ground of K-101 should again be ZERO.
- #2. Squelch Test and Push to Talk:
  - a. Set VOX gain R-140 to maximum.
  - b. All other gain controls to minimum.
  - c. Increase Carrier Insertion R-106 until Exciter Lamp lights.
  - d. Place Squelch Gain R-129 to maximum.
  - e. Commet AF generator unbalanced output to Terminals 13 and 14 of E-101. With the generator set to 1900 eps adjust its output until the Exciter Lamp extinguishes.
  - f. With the VTVM measure the voltage at Pin 9 of V110 it should be between .5 to 1.0 volt.
  - g. To simulate closing of the Push to Talk eircuit short terminal 1 of E-101 to ground. The Exciter Lamp should light and Relay K-101 should operate. Repeat for Pin 3 J-101.
  - h. Return VOX gain and Squelch controls to minimum.

## \*G. M.F. ALIGNMENT-INJECTION-CARRIER BALANCE

- \*1. Mid Frequency Alignment.
  - a. At the mixer grid of V113 there may app ar two frequencies, a 270Kc frequency (carrier ins rt d) and a VMO injection frequency. At the band extremes the following table applies.

XTAL OR VMO	DIAL READING	LF	RESULTING FREQ.
2000 Ко	2.0 Mc	270 K	1.73 Mc
11000 К	4.0 Mc	270 Ke	3.73 M

NOTE: Indicate compl tion and a ptan e f p rtion(s) of this t st prec ded by (\*) by recording required obs rved valu or by check (/) mark as re rded on attached test Data She ts.

DATE 8-24-64 SHEET 8 OF 18		TMC SPECIFICATION NO. 5 -410	
COMPILED	CHECKED	TITLE: Production T st of Model SBE-2	
APPROVED			

- b. The MID FREQUENCY is aligned so that the proper product is chosen when the dial is set to the VMO or XTAL frequency, that is, when a 2000 Kc xtal is inject d, the MF dial is set to 2.0 Mc but the actual frequency is 1.73 Mc which is the difference between the 2000 Kc xtal and the 270 KC LF. With this in mind, preliminary alignment may be accomplished by using the 2000 Kc and 4000 Kc xtals (or VMO).
- c. Before aligning the MF, see that the tuning capacitors are in full mesh when the dial is set to the mark r on the MF dial.
- d. Remove Pl07 from Jl10 on Zl07. Connect VTVM t Pin 2 of Zl07. Unbalance injection with Rl30, MF Balan Control.
- e. Select xtal pesition 1 (2000 Kc). Set MF dial t 2.27 MC. Tune T-109 and T110 for maximum output.
- f. Select xtal position 2 (4000 Kc). Set MF dial to 4.27 MC. Tune trimmers Cl40 and Cl41 for maximum output.
- g. This preliminary alignment will ensure subsequent selection of the proper mixer product on the MF dial.

## #2. Carrier Balance.

- a. Select xtal position 1 (2000 Kc)
- b. MF dial to 2.27 Mc.
- c. Carrier Insert CCW, adjust R130 for minimum carri r as indicated by observing Meter in MF position. L ck R130. Reconnect P107 to J110.
- d. Correct MF alignment will be indicated when a signal indication is noted on the MF dial at 2.0 mc and 2.54 mc with carrier inserted and Xtal Position 1.
- Set MF dial to 2.0 Mc. Tune Tl09 and Tl10 for maximum output. Select xtal position 2 (4000) Kc. S t MF dial to 4.0 mc. Tune Cl40 and Cl41 for maximum output in each case reduce the carrier to insur that proper mixer product has been selected. Repeat until band is track d. Lo k slugs with spintite to ls.

NOTE: Indicate compl tion and acc ptance of portion(s) of this test pre ded by (\*) by recording r quired observ d value or by check (/) mark as requir d on attach d test Data Sh ts.

DATE 8-24-64 SHEET 9 OF 18		TMC SPECIFICATION NO. S-410	E
COMPILED	CHECKED	TITLE: Produ tion T st of Model SBE-2	•
APPROVED			

## #3. Crystal and VMO Injection Check.

- a. Connect the VOX-5 output from the PTE analyser to VMO imput J104. Maintain a .1 on VOX-5 output meter level for all subsequent tests.
- \*b. Connect the RF voltmeter at the junction of Cl63 and Cl64 and measure the voltages under orditions indicated below:

S-107 Position	Freq.	Min. Voltage Limit
1	2.0 me	1.5 V.
2	4.0 me	.6 V.
VMO	2.0 me	1.5 V.
VMO	4.0 mc	.6 V.

## \*H. R.F. CIRCUITS ALIGNMENT

- #1. HF Oscillator and Multiplier Alignment.
  - a. Remove lead from J-108 and make connections from J-108 to RF VTVM.
  - b. All controls except "Power On" and "Exciter ON" switches in OFF Position or minimum.
  - e. Adjust L101 through L114 for meximum indication on RF VTVM at the corresponding "Injection" Fr quency shown below. Output requirement is not less than 3. volts.
  - d. Remove VTVM and sommest frequency Counter to J-108.
  - e. Adjust C-233 through C-240 for the corr et frquency as indicated by the Frequency Count r for the frequencies shown in "Injection" C lumn below.
  - f. Repeat above until frequency and output v ltages are correct. Reconnect PlO5 to JlO8.

NOTE: Indicat compl tion and a eptance f portion(s) of this test pre d d by (\*) by r cording required obs rv d valu or by ch ck (/) mark as required on attach d t st Dat She ts.

DATE 8=	24-64 of 18	ТМ	C SPECIFICATION NO. 5-410	E
COMPILED	CHECKED	TITLE:	Produ tion T st of Mod 1 SBE-2	
ADDD	OVED			

BAND MC POS.	XTAL F. (mc)	INJECT F. (mc)	<u>adjustments</u>	REMARKS
4	8	8	C233 L101	NOTE
2 6 7	10 12	10 12	C234 L102 C235 L103	When adjusting il
8	14	14 16	C236 L104 L105	slugs L101 thru L114
10	18 10	18 20	C237 L106 L107	way out and adjust on the first peak
11 12	11 12	5th 55	C238 L108 L109	indication.
13 14 15	13 14	24 <b>26</b> 28	C239 L110 L111	
16	10 8	30 32	L112 L113	
17	17	34	C240 L114	

- 2. Preliminary RF Amplifier Alignment:
  - a. Before alignment, check full meshing of capacit rs C-181 against dial marking at low frequency end of dial.
  - b. Channel 1 and 2 selector switches OFF.
  - e. XTAL Switch Position 3 (2.270 mc), Carrier Insert set for maximum, CW.
  - d. MF Tuning tuned at 2.270 mc. Meter in MF Position.
  - e. RF Output terminated in 70 Qload.
  - f. RF Voltmeter across 700 load.
  - g. In subsequent RF alignment tests the drive should be sufficiently low to preclude broad response met r indications.
- 3. 2-4 MC Band Alignment:
  - a. Output Tuning Bandswitch to 2-4 Mc Band.
  - b. Band MC Switch to Band O. MF Tuning to 2.27 me. M ter in MF Position.

NOTE: Indicat compl tion and acceptance of p rtion(s) of this test preceded d by (\*) by r ording required obs rv d value r by check (√) mark as requir d on attached t st Data Sheets.

DATE 8=24 HEET 11	-64 o <u>F18</u>	TMC SPECIFICATION NO. 5 -410	LILL
COMPILED	CHECKED	TITLE: Production Test f Mod 1 SBE-2	
APPR	OVED		

- c. RF Tuning tuned to 2 MC, RF Meter switch in RF output position.
- d. Tune T-116 and T-120 for maximum output.
- e. XTAL position 4 (4.270 mc), carrier inserted and MF Tuning tuned to 4.270 mc on MF Meter position.
- f. RF Tuning tuned to 4.0 mc. Meter in RF position.
- g. Peak C-191 and C-179 for maximum output.
- h. Repeat above steps to insure proper band alignment with reduced drive to insure sharp tuning peaks.

## 4. 4-8 MC Band.

- a. Output Tuning Bandswitch to 4-8 MC Band.
- b. Tune MF to 4.270 me, Output Tuning tuned to 4 m., RF Meter Switch in RF Output position.
- e. Tune T-113, T-117, and T-121 for maximum output.
- d. Carrier insert CCW, minimum carrier.
- e. MF XTAL Switch in VMO position (remains in this p sition for subsequent RF band alignments).
- f. Band MC Switch in Band 4. (8MC)
- g. Output tuning tuned to 8 MC.
- h. Peak capacitors C-203, C-192 and C-180 for maximum output.
- i. Repeat above procedure to insure proper band alignment with reduced drive to insure sharp tuning peaks.

## 5. 8-16 MC Band.

- a. Output Tuning Bandswitch to 8-16 MC Band.
- b. Output Tuning tuned to 8 MC. Meter switch in RF position.

NOTE: Indicat completion and acceptan of portion(s) of this test pr ce d d by (\*) by r cording required obs rved value or by ch ck (/) mark as r quir d on attached test Data Sh ts.

DATE 8-2	0F_18	TMC SPECIFICATION NO. 5 410	
COMPILED	CHECKED	TITLE: Production Test of Model SBE-2	
APPR	OVED		

- c. Band MC Switch in Band 4 (8 MC).
- d. Tune T-115, T-119 and T-122 for maximum output.
- e. Band MC Switch to band 8 (16 MC)
- f. Output Tuning tuned to 16 MC. Meter switch in RF position.
- g. Peak capacitors C-202, C-190 and C-718 for maximum output.
- h. Repeat above precedure to insure proper band alignment with reduced drive to insure sharp tuning peaks.
- 6.. 16-32 MC Band.
  - a. Output Tuning Bandswitch to 16-32 Band.
  - b. Output Tuning tuned to 16 MC. Meter switch in RF Position.
  - c. Band MC Switch in Band 8 (16MC)
  - d. Tune T-114, T-118 and T-112 for maximum output.
  - e. Band MC Switch to Band 16 (32MC)
  - f. Output Tuning tuned to 32 MC, and RF Meter Switch to RF Output position.
  - g. Peak capacitors C-201, C-189 and C-177 for maximum output.
  - h. Repeat above precedure to insure proper band alignment with reduced drive to insure sharp tuning p aks.
- #7. Output Voltages and HF Carrier Balance.
  - a. Carrier insert CCW, minimum.
  - b. Band MC Switch to Position O, RF tuning tuned t 18MC.
  - c. RF Output Control set for mid scale reading on met r in RF position.

- NOTE: Indicat completion and acc ptanc of portion(s) of this test pre d d by (\*) by r rding requir d bs rved value or by he k (\*) mark as required on attached test Data Sh ts.

DATE 8-2 SHEET 13	OF_18	TMC SPECIFICATION NO. 5 -410	H
COMPILED	CHECKED	TITLE: Produ tien T st of Model SBE-2	
APPR	OVED		

- d. Balance R-150 of Z107 for minimum indication on RF output meter.
- e. Band MC Switch to band O
- f. Set xtal selector switch to position 3 (2.270 Mc)
- g. With carrier inserted, tune MF to 2.270 Mc as indicated on Meter in MF Position.
- h. Audio generator connected to terminals 6-8 of E-101 Carrier Insert to CCW, LSB or USB gain set for 100% on MF Meter.
- i. Set RF bandswitch to 2-4 MC range. Tune output amplifier to 2 Me. Observe VTVM.
- j. Check for 10. V minimum across 70 Q load.
- k. The above Output Veltage test procedure must be r peated in two (2) megacycles increments from 2 through
  32 Mc, each time checking that a minimum 10 volt RF
  output is obtained across the 70\_0lead.
- 1. When performing above tests insure dial calibration is correct.

# I. OVERALL TESTS & REQUIREMENTS

- \*1. Power Output & Signal to Distortion Test.
  - a. This test will be made on one frequency s 1 cted at random in each one of the four RF Bands, n to sheet 18 of 18, Data Sheet.
  - b. Commet the two AF test tomes from the PTE analyser with a twisted shielded pair t Chann l linput, terminals 6 and 8 of E-101 with the shi ld commetted to terminals 7 and 5. Commet th analyser RF input to the Momiter Jack J102.
  - c. With the USB selector set to channel 1 and USB gain set to about -6 db, tune the unit to the s 1 ct d output frequency for an output of 8.4 RF volts across the 70 Qlead.

FOTE: Indi ate completion and a ceptane f p rtion(s) f this t st prec d d by (\*) by recording requir d observed value r by check (/) mark as required on attached test Data Sheets.

DATE 8-24- SHEET 14	-64 0F18	TMC SPECIFICATION NO. S 410	E
COMPILED	CHECKED	TITLE: Production Test of Model SBE-2	
APPR	OVED		

- d. Setup and adjust PTE as follows to measure the S/D in the USB;
  - (a) Gain fully clockwise.
  - (b) Amplitude scale switch to LOG.
  - (c) CAL OSC to OFF.
- e. IF attenuator to 20 db Position.
- f. Sweep selector to 14 Kc.
- g. AFC to OFF.
- h. The VOX-5 in the PTE should be adjusted for a frequency 500 kc higher than the signal frequency to be displayed. The two tone test signal should be set to the center of the analyzer.
- i. Adjust input attenuator switches so that two tone test signal peaks are as close as possible to the O line or slightly above. With the gain control set these peaks to the O line on the analyzer.
- j. Place IF attenuator switch to 0 position thus expanding the 0 to 40 db scale to 0 to 60 .
- k. Turn USB switch to OFF and adjust R109 and C119 of Z106 for maximum carrier suppression. Must be at least 55db down.
- L. Turn USB switch ON and note distortion products.

Requirement: The S/D must be at least 45 db below either tone of a standard two tone test for 1 watt PEP output as viewed on a PTE Panalyzer.

- \* 2. Carrier Suppression.
  - a. This test will be performed on the same frequencies as the test in paragraph 1 above and with the same general PTE Setup.
  - b. Turn USB and LSB switches to OFF, no AF input.
  - c. Tune the unit to the desired frequency with carrier insert drive for 1 watt PEP output. Carrier presentation in center of analyzer and peak adjusted to the 0 line with IF 20 db attenuator IN.

Note: Indicate completion and acceptance of portion(s) of this test preceded by(\*) by recording required observed value or by check ( mark as required on attched test data Sheets.

DATE 8-2 SHEET 15	4-64 oF18	TMC SPECIFICATION NO. 5-410	E
COMPILED	CHECKED	TITLE: Production T st of Model SBE-2	
APPR	OVED		

\*d. Set IF attenuator switch to 0 and place carri r insert fully CCW, carrier drive at minimum. N te level of the remaining carrier on analyser.

Requirement: Maximum carrier suppression must b at least 55 db below the test signal at 1 Watt PEP.

- \*3. Unwanted Sideband Rejection.
  - a. This test will be performed on the same fr quenci s as the test in Paragraph 1 above and with the sam general PTE setup.
  - b. Connect 500 ~ AF to terminals 6 & 8 of E-101, USB Channel 1 adjusted for -6 db and unit tuned t desired frequency for 1 watt PEP. PTE sweep at 14 Kc adjust presentation of 500 ~ tone signal to 0 line on analyser with IF 20 db attenuator in.
  - c. Set LSB to Channel 1. This will provide a dual  $500 \, \sim$  tone signal presentation. Note position of the LSB  $500 \, \sim$  tone signal and then place LSB to OFF.
  - \*d. Set IF 20 db attenuator to 0 and read the 1 vel f the 500~tone appearing as an unwanted signal in th LSB.
  - \*e. Repeat the above test for the LSB.

Requirement: Unwanted Sideband rejection shall be at least 60 db below 500 ~ ton test signal for 1 Watt PEP, both USB and LSB.

- \*4. 2nd Harmonic Suppression.
  - a. This test will be performed on a frequency in the 4-8 mc band.
  - b. Set both LSB and USB OFF and tune the unit with carrier drive to 1 Watt PEP output at the 2nd Harmonic of the fundamental frequency to b measured. (Example: -If desired frequency to be measured is h

NOTE: Indicate completion and acceptance of portion(s) of this test preceded by (\*) by recording required observed value or by check () mark s required on attach d t st Data She ts.

DATE 8-2 SHEET 16	0F 18	TMC SPECIFICATION NO. S -410	E
COMPILED	CHECKED	TITLE: Production T st f M del SBE-2	
APPR	OVED		

MC, the unit would be tuned to 8 MC).

- e. Adjust presentation on PTE with IF 20 db attenuat r IN and signal peak on 0 line. Leave all PTE ontrels at their present settings.
- d. Tune the unit to the fundamental frequency at the sam output as above.
- we. Set the IF 20 db attenuator to 0. The 2nd harmonic component will now be presented on the analyz r. Note the level of this 2nd harmonic signal.

Requirement: The 2nd harmonic shall be at least 40 db below the level of the fundamental frequency at 1 Watt PEP output.

## \*5. Frequency Response Test.

a. Setup AF generator to approximately the cent r frequency of the bandpass spectrum (1650 ~) at .05V output connected to terminals 6 and 8 of E-101., with shielded twisted pair, shield connected to 7 and 5. Menitor AF Generator output with Heath Kit AV-3 VTVM. Output should be constant.

b. Connect VTVM at the LSB filter Z101 terminal 5 to ground.

- c. Advance LSB gain control to -6 db and adjust RF Output for center scale reading on VTVM.
- d. Maintaining constant output from the AF generator vary the frequency from 350% to 3300% noting the maximum and minimum readings indicated by the VIVM.
- e. Repeat above test for the USB with AF generator connected to terminals 10 and 12 on E-101 with the ground shield tied to terminals 11 and 14 and the VTVM connected at USB filter terminal 5 to ground. Requirement: The difference between the maximum and minimum readings in step 5 above shall not exceed 3 db for LSB and USB.

NOTE: Indicat cmpl tien and ac ptance of p rtion (s) f this test prec d d by () by r rding r quir d ebs rved valu or by h ek () mark as required on attached test Data Sh ts.

DATE	8-	5H- <del>9</del> H				- 130	
SHEET_	17	ог <u>18</u>	TMC	SPECIFICA	TION NO	D. S 4410	E
СОМРІ	LED	CHECKED	TITLE:	Production T	st of Mede	ol SBE-2	
	APPR	OVED		TEST DATA S	HEET		
1.	(A=	l thru 8) P	reliminary	check & tests	complete	đ	(h)
2.	•	17 Ke OSC.	•	• .			-
2.	(5)	I NO ODO	(1)	Output Voltag Frequency	<b>ξ</b> Θ	Kc +	_v. ~_
3•	(C)	287 Ke 080	(1)	Output Voltag Frequency		Kc +	v. ~
4	(D)	Medulator	Tests.				
			B Bal. comp OSC. and 2 adjustm	leted 70 Ke amplifi ents complete	ler d		_(X) _(X)
5.	(E)	Audio & S	ideband Rev	ersal	•		
		(2) Chanz	phone input el 1 input el 2 input	completed			
6.	(F)	VOX Tests	· I•				
				y operation of the checken			[W
7.	(G)	MF ALIGN	ent				
		(2) Carri	er Balance	t Completed completed (a on at 2MC		cv.	-(X) -(X)
8.	(H)	RF Circui	ts Alignmen	t			
		(7) Outpu	C and Multi it Voltages ies obtaine	acress 70Al	ent comple oad for fr	ted	_63
2	MC		v. 14	MC	v.	26 MC	_v.
4	MC_		v. 16	MC	v.	28 MC	v.
6	MC_		_v. 18	MC	v.	30 MC	<u>v</u> .
8	MC		_v. 20	MC	v.	32 NC	_v.
10	MC_		_v. 22	? MC	v.		
12	MC_		v. 24	MC	v.		

EET 18	-64 of18	-   -	ГМС	SPI	ECIF	'ICA'	ΓΙΟΝ	NO	. <b>5-</b> 410
OMPILED	CHECKED	TITL	E:	P <b>rodu</b>	tien	T st	of Mo	del	SBE-2
APPROVED					Test	DATA	Sheet		
	(H) OVER	ALL I	ests	& REQ	UIREM	ents			
		F	MAD	E AT	l Wat	T PEP	OUTPU		
	SW	OUT	s/d	R <b>atio</b>	MAX	GAR	UNWAI SB.	ited Rej.	SECOND HARM
		mcs,	USB	LSB	ďb		USB	LSB	REJ.
	2-4 mcs	•							
	4-8 "			<b>†</b>					
	8-16 "	***************************************			<b></b>				
							}		
	16-32"	<del></del>							
	POWER OU	ents:	70 4	<b>loa</b> d	with	8.4			of a two i
	<b>2.</b> S	,	,	`_ <b>T</b> _,`		DED.	_	0.0210	01 4 040 (
	b. M 5. U 6. U 1 d. 2	est s aximu 5 db nwant 0 db watt nd Ha	m Car below ed Si below PEP. rmoni	rier : the : demand 500~ c Rejo	Suppresignation Rejection	essica lat : estica test	n at ] l watt n at ] signs least at ]	PEP. least il at	
	b. M 5 6. U 6. 2 b	est s aximu 5 db nwant 0 db watt nd Ha elow	m Car below ed Si Below PEP. rmoni two t Fre	the state of the s	Suppresignation of tone oction	ession lat : ection test nat : ignal ponse ib (+	l waten at l signs least at l from 12 db	PEP. least il at 40 di watt 350	PEP.
	b. M 5 6. U 6. 2 b	est s aximu 5 db nwant 0 db watt nd Ha elow	m Car below ed Si Below PEP. rmoni two t Fre	the state of the s	Suppresignation of tone oction	ession lat : ection test nat : ignal ponse ib (+	l waten at l signs least at l from 12 db	PEP. least il at 40 di watt 350	PEP.
MFG.NO.	b. M 5 6. U 6. 2 b	est s aximu 5 db nwant 0 db watt nd Ha elow	m Car below ed Si Below PEP. rmoni two t Fre- flat Max. Va	the state of the s	Suppresignation Rejudent Suppresignation Response Suppresignation Respo	essication test  n at lignal ponse db (+ (1) (2)	l watth at 1 signs least at 1 from 12 db	PEP. least 1 at 40 dr watt 350	PEP.
	b. M 5 6. U 6. 2 b	est saximum 5 db nwant 0 db watt nd Ha elow 3300 ^	m Car below ed Si Below PEP. rmoni two t Fre- flat Max. Va	the state of the s	Suppresignation Rejudent Suppresignation Response Suppresignation Respo	essication test  n at lignal ponse db (+ (1) (2)	l watth at 1 signs least at 1 from 12 db	PEP.  east  40 dh  watt  350	PEP. to  DB

REVISION SHEET

# THE TECHNICAL MATERIEL CORP. MAMARONECK NEW YORK

S-410

MODEL SBE-2

PROJECT NO. -

DATE	REV.	PAGE	EMN#	DESCRIPTION	снк.	AP
/31/62	A	7 3	6991	Chg. No. 3 to "A"		Ţ
		<u> </u>		Add "III PROCEDURE"		
		5		Add letter "B" to "TITLE"	11	
			ļ	Add No. 1 to remark,		
				Add letter "C" to "MICROPHONE INPUT" Sect.		
		6		Add letter "D" to "CHECK INPUTS" Sect.		
				Add No. 1 on "CHANNEL 1"		
		<u> </u>		Chg. No's. to letters	11	
		7		Number "CHANNEL 2, No. 2		
				Letter "17KC CARRIER BAL." Sect. "E"		
	· 	8		Letter "CARRIER RE-INSERTION" Sect. "F"		
				Letter "VOX SQUELCH" Sect. "G"	11	
	-4.	9		Add letter "H" to "PUSH TO TALK" Sect.	11	
				Number"287KC"Sect.	11	<b>-</b>
		10		Add letter "J" to "AMPLITUDE MOD. SIMULATION TEST"	11	
				Sect.	1	1
				Add letter "K" to "FINAL CHECK" Sect.		
		11		Add letter "L" to "MID FREQ. CRYSTAL" Sect.	<del> </del>	,
				Add letter "M" to "MID FREQ. ALIGNMENT" Sect.	1	-
		12		Number "MID FREQ. ALIGNMENT" Sect.	1	1.7
				Add letter "N" to "SETTING OF C258" Sect.		
		13		Add letter "O" to "MID FREQ. CARRIER BAL." Sect.		
				Add letter "P" to "FINAL AMPLIFIER ALIGNMENT" Sect.		
				Add letter "Q" to "3-4MC BAND ALIGNMENT" Sect.		
		14		Add letter "R" to "4-8MC BAND ALIGNMENT" Sect.	++-	
		15		Add letter "S" to "8-16MC BAND ALIGNMENT" Sect.		
				Add letter "T" to "16-32MC BAND ALIGNMENT" Sect.	1-1-1	
		<b>1</b> 6		Chg. from "FINAL TEST" Sect. to "OUTPUT TEST" Sect.		
				Add letter "U"	1 1	<del></del>
		17		Renumber items 1,2, add No. 11	+ + +	
		18.19.2	0	Add sheets 18,19,20	1-11	
		all pages		Renumber all pages from 1 of 17 to 1 of 20	<del>                                     </del>	
/64	В		12308	Revised completely per EMN		11
164	С		12463	SH 5,6,14,15 Revised per EMN	† †	K
0/64	D	4	12828	Revised sht. 4 per EMN	1 - 1	Z
6/65	E			Revised shts, 16 and 18 per EMN		1
T.				DOL MANI	<del>                                     </del>	9