

TOTAL SHEETS 3
6

REV 0 18 NOV. 1968.
A 26 NOV. 1968.
B 13 DEC. 1968.
C 5 FEB. 1969
D 22 FEB. 1969.
E 26 MAR. 1969.
F 28 July, 1970.

MODEL
A10714-5
A 10714-6.

TITLE
PRINTED CIRCUIT ASSEMBLY
OUTPUT

USED ON SECTION QTY.
1
4

MODEL
AMC 8
AMC 32

- LIST SECTIONS
1. SUPPORTING NOTES
 2. SUPPORTING LISTS
 3. ELECTRICAL/MECHANICAL
 4. SUPP ASSY/REF DWGS
 5. SPECIFICATIONS
 6. LOOSE ITEMS
 7. PARTS PECULIAR

SHEET NO.
SEE BELOW

COMPILED
CHECKED
APPROVED
FNL APPR
ISS DATE

Watson
Rail
WA
19 NOV 1968

MATERIAL LIST/NUMERICAL PARTS LIST

TOTAL SHEET 1 OF 3

REV

USED ON MODEL: AMC 8, AMC 32

USED ON SECTION:

ASSY SHEET 1 OF 3

NEXT ASSY: QTY PER NEXT ASSY: ASSY LEVEL: ASSY DESC: PRINT CIR ASSY OUTPUT (75~) ASSY PART NO: A10714-5

LIST SECTION

PART NO.	DESCRIPTION	ITEM LOCATION			QTY. PER ASSY.	REFERENCE SYMBOLS	REMARKS
		USED ON ASSEMBLY	USED TO MOUNT	QTY PER U/T/M			
A10714-1	PRINT CIR BRD ETCH	A10714-2			1		
A10714-2	" " " MACH	A10714-3			1		
A10714-3	" " " MKG	A10714-4			1		
A10714-4	" " " S/A	A10714-5			1		
CC10015-X5V104M	CAP, FXD, MICA	A10714-5		4	18	C1, 2, 12, 13,	
				4		C22, 23, 32, 33,	
				4		C42, 43, 52, 53,	
				4		C62, 63, 72, 73,	
				2		C82, 83.	
CC10017-X5V103M	CAP, FXD, MICA	A10714-5		4	8	C11, 21, 31, 41,	
				4		C51, 61, 71, 81,	
CK10682	SCHEMATIC	A10714-5			1		
CL275-221	COIL FXD, RF	A10714-5		4	8	L12, 22, 32, 42,	
				4		L52, 62, 72, 82.	
CL275-330	COIL FXD, RF	A10714-5		4	8	L11, 21, 31, 41,	
				4		L51, 61, 71, 81.	
FWO2HSS	WASHER, FIAT	A10714-5			16		

MATERIAL LIST/NUMERICAL PARTS LIST

TOTAL SHEET 2 OF 6

ASSY SHEET 2 OF 3

USED ON MODEL: AMC 8, AMC 32

USED ON SECTION:

ASSY PART NO: A10714-5

REV

NEXT ASSY:

QTY PER NEXT ASSY:

ASSY LEVEL:

ASSY DESC:

PRINT, CIR ASSY, OUTPUT (75 ~)

ITEM LOCATION

QTY. PER ASSY.

REFERENCE SYMBOLS

REMARKS

PART NO.

DESCRIPTION

USED ON ASSEMBLY

USED TO MOUNT

QTY PER U/T/M

GL138

COMPOUND, HEAT SINK

A10714-5

X

HD10004

HEAT SINK

A10714-5

8

LWE02MSS

WASHER, LOCK EXT

A10714-5

16

RC07GF101J

RES, FXD, COMP

A10714-5

4

8

R11, 21, 31, 41,

4

R51, 61, 71, 81.

RC07GF332J

RES, FXD, COMP.

A10714-5

4

8

R13, 23, 33, 43,

4

R53, 63, 73, 83.

RC07GF432J

RES, FXD, COMP.

A10714-5

4

8

R12, 22, 32, 42,

4

R52, 62, 72, 82.

RN60D71R5F

RES. FXD. FILM

A10714-5

4

8

R15, 25, 35, 45,

4

R55, 65, 75, 85.

RC32GF221J

RES, FXD, COMP

A10714-5

4

8

R14, 24, 34, 44,

4

R54, 64, 74, 84.

SCBP0256SS4

SCREW MACH

A10714-5

16

TE10023-3

TERM STUD

A10714-4

20

Ottawa, Ontario

MATERIAL LIST/NUMERICAL PARTS LIST

TOTAL SHEET 5 OF 6.

REV

USED ON MODEL: AMC-8, AMC-32.

USED ON SECTION:

ASSY SHEET 2 OF 3.

NEXT ASSY:

QTY PER NEXT ASSY:

ASSY LEVEL:

ASSY DESC:

PRINT CIR. ASSY, OUTPUT. (50 ~)

ASSY PART NO:

A 10714-6.

PART NO.	DESCRIPTION	ITEM LOCATION			QTY. PER ASSY.	REFERENCE SYMBOLS	REMARKS
		USED ON ASSEMBLY	USED TO MOUNT	QTY PER U/T/M			
GL 138.	COMPOUND HEAT SINK.	A 10714-6.			8.		
HD 1000/.	HEAT-SINK.	A 10714-6.			8.		
LWE 02MSS.	WASHER LOCK EXT.	A 10714-6.			16.		
RC 07GF101J.	RES. FXD. COMP.	A 10714-6.		4.	8.	R11, 21, 31, 41,	
				4.		R51, 61, 71, 81.	
RC 07GF332J.	RES. FXD. COMP.	A 10714-6.		4.	8.	R13, 23, 33, 43.	
				4.		R53, 63, 73, 83.	
RC 07GF432J.	RES. FXD. COMP.	A 10714-6.		4.	8.	R12, 22, 32, 42.	
				4.		R52, 62, 72, 82.	
RN 60D52R3F.	RES. FXD. FILM.	A 10714-6.		4.	8.	R15, 25, 35, 45.	
				4.		R55, 65, 75, 85.	
RC 32GF221J.	RES. FXD. COMP.	A 10714-6.		4.	8.	R14, 24, 34, 44.	
				4.		R54, 64, 74, 84.	
SCBP0256SS4.	SCREW MACH.	A 10714-6.			16.		
TE 10023-3.	TERM STD.	A 10714-6.			20.		

